Quantum® + Hardcoated Polycarbonate VStream Windscreens for 2024 - current R1300 GS and 2025-current R1300 GS Adventure Models.



NATIONAL CYCLE Z2500 Low; Dark Tint / Z2501 Low; Clear / Z202 Tall; Clear

VStream® Windscreen Patent No. 7,387,328

Thank you for purchasing a ZTechnik product. Read these instructions carefully and thoroughly before beginning work. Dealers, if installing this windshield for a customer, please give them this manual upon completion. It contains information needed to properly maintain and use this product.

Descr iption:	VStream® Replacement Windscreen	Model:	2024-Current R1300GS / 2025-Current R1300GSA
Part Number:	Z2500 / Z2501/ Z2502	Installation Time:	20 min. Difficulty Level: Easy

CONTENTS OF KIT ITEM DESCRIPTION	
VStream Windscreen	1
Stainless Washer	4
Rubber Washer	4
	Stainless Washer

TOOLS REQUIRED ALL OEM FASTENERS
T-25 Torx Wrench WILL BE REUSED.







ATTENTION: Special notes and cautionary measures which can prevent damage to the accessory or vehicle.



NOTE: Tips for facilitation of operation, control and adjustment, as well as maintenance work.

Step 2

PREPARATION: Place motorcycle securely on it's centerstand.

Step 1: Using a T-25 Torx Wrench, remove the 4 mounting bolts that hold the OEM windscreen onto the mounting bracket. **The OEM screws and compression limiters will be reused.**

Step 2: Place 1 of the provided rubber washer onto each of the 4 OEM compression limiters. Then insert the compression limiters through the pre-installed rubber grommets in the back of the windscreen



Your VStream installation is complete.

Double-check your work for fit and tightness before riding.

Now go out and enjoy the ride!





Step 2 cont.



Step 3



ZTechnik by National Cycle, Inc. 708-343-0400 / Fax: 708-343-0625

2200 S. Maywood Drive, Maywood IL 60153-0158 USA www.ztechnik.com e-mail: info@ztechnik.com



CLEANING AND MAINTENANCE

To clean the screen, wash with a clean soft cloth and plenty of warm water and, if necessary, a non-abrasive soap such as dishwashing liquid. Flannel or soft chamois make good cleaning cloths. Paint, glue residue or grease removal: Moisten cotton wad with naphtha or turpentine followed by a wash as above.

National Cycle **Shield Wash™** (N1401-01) makes a good daily cleaner and comes with a handy travel-size bottle. Shield Wash is safe for all windshields and helmet visors

Do not clean polycarbonate in hot sun or high temperatures. Do not clean the screen with household glass cleaners. Do not allow brake fluid, alcohol, or strong solvents to contact the screen.

RAIN REPELLENT

Do not use rain protective products made for glass. We recommend National Cycle's **RainZip**® (N1410-01) to keep your windscreen clear in rainy weather.



Register Your Windshield Online at www.nationalcycle.com ZTechnik by National Cycle 3-Year Limited Warranty

National Cycle hereby warrants to the original registered owner of a National Cycle polycarbonate windshield for a period of three years from the date of purchase against break- age. This limited warranty is expressly limited to the replacement of the polycarbonate windscreen. This limited warranty does not include scratches, coating failure, cosmetic wear and tear, replacement of hardware, or any consequential damages or expenses including labor cost of installation, removal and/or replacement, inconvenience, inbound freight expenses or damage to any other component of the motorcycle or any other accessories. Certain chemicals, generally known as acidic hydrocarbons, are known to cause polycarbonate damage and will not be covered under this limited warranty. Please refer to the cleaning instructions supplied with all National Cycle windshields. Visit www.nationalcycle.com for further details, or call or e-mail National Cycle.

WARNING

Never ride your motorcycle with loose accessory mounting hardware. Check the hardware for tightness regularly. Today's motorcycles are built to withstand the moderate loads imposed on them by the foreseeable addition of an accessory(ies). If an accessory(ies) adversely affects your motorcy-cle's stability, immediately remove the accessory(ies). Do not ride a motorcycle that exhibits unsafe handling traits. Have experienced service personnel correct any problem before riding with the accessory(ies) installed. For further questions concerning handling problems associated with an accessory(ies), contact your dealer, motorcycle manufacturer, or accessory manufacturer. Sunlight reflected off the inside curvature of the windscreen can, at certain times of day, cause extreme heat buildup on the motorcycles instruments and possibly even melt them. Exercise care in parking to avoid this. Park your motorcycle facing the sun or place an opaque object over this area.

